



SIZE CHART



MEN'S TOPS

BODY MEASUREMENT IN INCHES								
SIZE	S	M	L	XL	2XL	3XL	4XL	5XL
NECK	14 1/2	15 1/2	16 1/2	17 1/2	18 1/2	19 1/2	20 1/2	21 1/2
SLEEVE LENGTH	32 1/4	33 1/2	34 1/4	35	35 3/4	36 1/2	37	37 1/2
CHEST	34-37	38-41	42-45	46-49	50-53	54-57	58-60	61-63

HOW TO MEASURE:

NECK

Measurement is the circumference of the neck as illustrated.

SLEEVE LENGTH

Measured by placing one end of the tape at bottom of the collar at the center of the back and marking the distance around the elbow to bottom of the wrist. It is often helpful to have the arm slightly bent.

CHEST

Taken at the fullest point of the chest, keeping tape under arms and around shoulder blades. Hold tape level and firmly but not tight.